


— Alloy E      - - - AA 2214      ····· AA 2219  
- · - - AA 2818

**Fig. 1**

2/5



$$LMP = [(T_{test} + 273.15) \cdot (20 + \log t_{fatigue})] / 1000$$

**Fig. 2**




Fig. 3





Fig. 4a

Fatigue strength at  $T_{\text{test}} = 200^\circ\text{C}$ 

Stress Reversals (-)

Fig. 4b